

REMEDIATION OF A PETROLEUM SPILL USING PURE OXYGEN

COLTER BAY VILLAGE MARINA TETON NATIONAL PARK, WY

John Archibald, inVentures Technologies, Inc J.S. Roemmel, SECOR International





iSOC[®] TECHNOLOGY

Microporous Hollow Fiber



Cross Section 200 µm



Inner Surface 1 µm

Mass Transfer Device



How Does It Work?

- 700 Hollow fibers filled with holes
- Provides large surface area for mass transfer (7000 sq ft per cu ft)
- Mass transfer occurs when gas pressure is less than GW
- GW in well is saturated with high DO (without bio-sparging)
- High DO levels migrate to surrounding biomass
- Microbial population increases
- Microbes degrade targeted compounds







iSOC[®] DISSOLVED GAS CONCENTRATIONS (ppm)

Atmospheric Pressure Determines DO Levels

Gas Type	Water Column Depth (ft)					
	5'	10'	15'	20'	50 '	
Oxygen	42	55	62	69	111	
Methane	22	30	33	37	59	
Propane	66	88	99	110	175	
Hydrogen	2	2	3	3	5	
Ethane	57	75	85	95	150	

iSOC[®] by inVentures Technologies

iSOC® TREATMENT PROCESS



- Install up gradient of source, in the plume or cut-off curtain
- Screen injection well in target zone
- DO disperses around well and into groundwater
- GW velocity, oxygen demand of aquifer and molecular dispersion affect ROI
- Supersaturates well with Dissolved Oxygen (DO) 40 to 200 PPM depending on depth of iSOC[®] in the well
- High DO stimulates microbes to remove target compounds

TYPICAL iSOC WELL SCHEMATIC







TETON N.P. GROUND WATER REMEDIATION SYSTEMS

Park Locations

Signal Mountain Lodge: SVE,Ozone Sparge Leeks Marina: SVE, Ozone Sparge Flagg Ranch: SVE, Sparge *Colter Bay Marina: iSOC® System*



SITE GEOLOGY

Glacial till (moraine)

Poorly sorted gravel, sand, silt, cobbles

Unknown, but large depth to bedrock



GROUND WATER CONDITIONS

- Depth to water table fluctuates from 11 ft 30 ft below ground surface
- Hydraulic conductivity 2.3 x 10⁻⁵ ft/sec
- Generalized flow across site west to southwest toward Jackson Lake
- In 2000, petroleum contamination plume extended 250 ft downgradient of UST basin, with maximum width of 110 ft.





PETROLEUM RELEASE HISTORY

- Release of gasoline and diesel from 2 USTs and product line
- 2 steel tanks installed in 1975, removed in 1994
 - 1992 failed tightness test for Tank 1 product line
 - Large hole observed in Tank 1 during removal
 - No holes observed in Tank 2
 - Soil discoloration, moderate petroleum contamination in soils
- 2 replacement tanks installed in May, 1995 (same tank pit)





EXTENT OF CONTAMINATION - 2000



iSOC® by inVentures Technologies



GEOLOGIC CROSS-SECTION - 2000





REMEDIATION ALTERNATIVE ANALYSIS

Alternative #1:

Monitored Natural Attenuation (MNA)

Alternative #2:

Enhanced Natural Attenuation – iSOC[®] Technology

Alternative #3:

Ozone Sparging/SVE Venting



CRITERIA FOR ALTERNATIVE #2 (iSOC[®]) SELECTION

- Protective of human health and environment
- No electric power supply requirement onsite
- No noise impacts to Marina/National Park visitors
- Technology proven to work in cold climates with no freeze-ups
- Remediation projected to be completed within 3 years







ALTERNATIVE #2 – iSOC® TECHNOLOGY



iSOC[®] by inVentures Technologies



COLTER BAY MARINA SITE MAP



iSOC[®] by inVentures Technologies



iSOC® by inVentures Technologies











MAY, JUNE 2005 OXYGEN PARAMETERS

May 2, 2005

1	1	I.	1	
	MONITOR WELL NUMBER	OXIDATION- REDUCTION POTENTIAL (ORP)	DISSOLVED OXYGEN (DO) ppm	
	2	+ 94	0	
	3	+ 137	0	
	4	+ 217	2.77	
	_		-	
	5	+ 228	0	
			• •	
	6	+ 212	2.9	
	0	. 070	0.05	
	8	+276	3.25	
JUNE 21, 2005	iSOC Injectio	n Well Random DO	D Measurements (p	opm)
	,			
	INJECTION WELL NUMBER	DISSOLVED OXYGEN (DO) ppm	LOCATION	
	IW-3	54 ppm	Near Tanks	
	IW-7	16.1 ppm	Near Lake	

iSOC[®] System installed June, 2004

www.isocinfo.com

iSOC[®] by inVentures Technologies

May 2, 2005: Oxidation-Reduction Potential in Monitor Wells



iSOC[®] by inVentures Technologies

Teton National Park, WY Monitor Well Results

Colter Bay Marina Site, WY Monitor Well Results

Та	ink Bas	in Area V	Vells			Near L	ake	We	lls	
	2000-2002 pra-150C	ISOC Installed Oct 2004	May 2005	May 2006		2000-2002 pre-150C	SOC In Oct 2	stalled 004	May 2005	May 2006
Benzene	49-310		4-28	BDL	Benzene	1-190			BDL-5	BDL
Toluene	1200- 1300		151- 2820	BDL	Toluene	<1-16			BDL- 18	BDL
Ethyl- benzene	380-430		104- 584	BDL	Ethyl- benzene	<1-73			BDL	BDL
Xylenes	1700- 3400		788- 3260	BDL	Xylenes	<2-7			BDL- 58	BDL
Naphthalene	79-110		26-102	BDL	Naphthalene	<5			BDL	BDL

iSOC[®] by inVentures Technologies



TETON N.P. GROUND WATER REMEDIATION SYSTEMS

Comparison of Operating Efficiencies at Teton Park Sites

SITE/SYSTEM	PERCENT RUN TIME SINCE NOVEMBER 7, 2006
Signal Mountain Lodge SVE	88%
Signal Mountain Lodge Ozone Sparge	61%
Leeks Marina SVE	69%
Leeks Marina Ozone Sparge	17%
Flagg Ranch SVE	78%
Flagg Ranch Sparge	49%
Colter Bay iSOC [™]	100%

iSOC[®] Remediation Completed in 1.5 years





TETON N.P. GROUND WATER REMEDIATION SYSTEMS

Comparison of Operating Efficiencies at Teton Park Sites

SITE / SYSTEMS	PERCENT RUN TIME
Signal Mountain Lodge SVE	88%
Signal Mountain Lodge Ozone Sparge	61%
Leeks Marina SVE	69%
Leeks Marina Ozone Sparge	17%
Flagg Ranch SVE	78%
Flagg Ranch Sparge	49%
Colter Bay iSOC [®]	100%

iSOC[®] Remediation Completed in 1.5 years

iSOC[®] by inVentures Technologies Questions / Comments John Archibald (P): 905-339-1543 (E): john.archibald@inventures.ca