

The Importance of Considering Combined Surface Water and Groundwater Drainage Issues When Planning Site Remediation



Joe Lenham – Principal Consultant, Environment Tom Dance – Principal Hydrogeologist, Environment Tetra Tech EBA Calgary

Identifying the problem



SW corner of lease

complex world CLEAR SOLUTIONS"

Looking uphill (east)




complex world CLEAR SOLUTIONS"



Site History

Remediated areas: dig, clean, replace to 4-6 mbgs – over four years (2005-2008).



Water-bearing pipeline

Wet area (off-lease) White lines: pipelines

Initial Hypotheses for Cause of Wet Area (from kick-off discussion)

- 1. It's natural! 🭲
- 2. Water pipeline-related:
 - Pipe broke during remediation or site activity
 - Pipe broke before site purchase
 - Pipe is just leaky 🤞
- 3. Caused by site remediation but the wet area was not disturbed, so how?
- 4. Something and/or someone else entirely?

(Nobody was in agreement)



Plenty of Data and Information Sources

- 15 years of third-party monitoring reports
- Remediation activity reports
- Borehole/test pit/probe logs (>150)
- Hydraulic conductivity results from 26 wells
- Remediation reports, photographs
- LiDAR and aerial imagery
- Abacus Datagraphics plans
- Regional mapping, topo data etc.

Initial Difficulties

The existing data and reports were inconclusive, and supported multiple interpretations.

- **Exactly** where are the pipelines?
- No intrusive site access allowed.
- Primary data were inconsistent:
 - K values
 - GW levels
 - Geology
- Stereotypical response: "let's drill some more wells!".



Alternative: Painstaking Review Process


Strip it back to the bare bones. Test everything.

- Identify reliable data sources (imagery, LiDAR)
- Obtain original field notes. Check them.
- Follow the data trail through every report table.
- Identify gaps and inconsistencies.
- Cross-plot data to find anomalies.
- Construct a 3D spatial site model.

Then evaluate the initial hypotheses.




1950 Aerial Image



"It's natural". Job Done! (Is there a prize for the shortest RemTech talk ever?)

complex world

2009 LiDAR




Therefore, our wet area is in a long-standing depression, albeit sloping.

complex world CLEAR SOLUTIONS"



2000 Aerial Image




Yes, the site is naturally prone to the development of wet areas, but..... ...the question asked by our client wasn't, "*can we blame somebody else?*". It was: "*Was it us?*"



• Wet area is predisposed to gather water. Where from?

ETRA TECH EBA



complex world CLEAR SOLUTIONS

Pipeline Hypotheses


• It's natural!

RA TECH EBA

- Pipeline-related:
 - Pipe broke during remediation or site activity



- Pipe broke before site purchase
- Pipe is just leaky 🥧
- Caused by site remediation but the wet area was not disturbed, so how?
- Something and/or someone else entirely?




Pseudo-surface Showing Excavations at 4.5 m Depth

ETRA TECH EBA

complex world

LiDAR side-view



- the pipeline is not the cause.

Freshwater line

complex world



• It's natural!

ETRA TECH EBA

- Pipeline-related:
 - Pipe broke during remediation or site activity
 - Pipe broke before site purchase
 Pipe is just looky
 - Pipe is just leaky
- Caused by site remediation but the wet area was not disturbed, so how?
- Something and/or someone else entirely?




Groundwater Check

Before interpreting historical groundwater data, check:

- Borehole geology;
- Well locations;
- Ground and well top elevations;
- Screen materials;
- K values;
- Depths to water; and
- Calculations of GW elevation.

LiDAR check: time-lapse




TETRA TECH EBA

CLEAR SOLUTIONS"

Shaky ground...

Tip: read blue, then red



CLEAR SOLUTIONS"


Groundwater Levels Review / Honesty Check

Confession time.....

- 17 historical monitoring events. Obtained and reviewed field notes/report tables for 14.
- ~50% contained at least one transcription or calculation error.
- Worst event contained 9 errors in 16 measurements.
- Several wells' data had been swapped.
- One year's data doubly corrected for stick-up.
- Worst error was a 4m GW level shift.


Groundwater Levels Up-Slope From Remediated Zone

Precipitation increases



Wet area appears; worsens


complex world CLEAR SOLUTIONS"



TETRA TECH EBA

complex world CLEAR SOLUTIONS"

Boreholes: Sand




Till (clay)


Sand

Bedrock (sandstone, shale)

complex world







ETRA TECH EBA



- Natural conditions favoured wet area formation, but did not explain cause.
- Pipelines were not responsible.

TECH EBA

- After QA/QC, groundwater data told a clear story.
- Better visualization explained K test results.
- Only one hypothesis remained valid.

And the winner is....

- Thin sand layers dominated shallow GW flow.
- Remediation destroyed the soil structure.

RA TECH EBA

- Homogeneous clean soils were compressed tightly.
- Groundwater "piled up" by ~3.5 m behind the obstruction, like this:



Problem identified!

What happened next?

- Additional temporary wells confirmed GW levels extended to wet area.
- Confirmed that groundwater/surface water interaction was the problem.
- Now our client was empowered to improve the situation.
- Substitute drainage is being installed on the existing leased land.
- We received a compliment \bigcirc .

RA TECH EBA



Check everything!

ETRA TECH EBA

Thanks for listening!

Joe Lenham PhD, C.Geol. Principal Consultant Tetra Tech EBA, Calgary jlenham@eba.ca