


Giant Mine Remediation Project

RemTech,
Banff, AB Oct 2009





Original Giant Mine
"A" Shaft



• Giant Mine History

- Several companies owned and operated Giant Mine for 55 years. 1948 - 2004
- 7.6 million ounces gold were produced by roasting arsenopyrite
- Ultimately, bankruptcy of the last two mine operators left Indian and Northern Affairs Canada (INAC) and the Government of the Northwest Territories (GNWT) responsible for the site.
- The former mine lease area is now a reserve issued to INAC by the GNWT.
- The site is currently under the care and maintenance of INAC/PWGSC



“C” Shaft
Headframe



■ **Legacy of mining activity**

- Contaminated surficial materials (arsenic and hydrocarbon)
- Buildings with severe arsenic contamination, asbestos insulation
- Decaying mine infrastructure
- Tailings impoundments, sludge settling and polishing ponds
- Toxic arsenic trioxide dust in underground storage (237,000 tonnes)

Giant Mine



Giant Mine Reserve 846ha



- NWT Commissioner's Land
- Within Yellowknife City Limits
- Includes Town Site



Indian and Northern
Affairs Canada

Giant Mine Remediation Plan


Site Location

PROJECT NO. 1C/001.013	DATE Jan. 2006	APPROVED MDR	FIGURE 1.1.1
---------------------------	-------------------	-----------------	-----------------




Ore Processing

- Refractory ore
- Arsenopyrite concentrate was roasted at high temperature ($\sim 500^{\circ}\text{C}$) to break down the mineral structure and liberate gold



Gold Extraction by Roasting

Arsenopyrite $\text{Fe}^{3+} \text{As S}$



As 46.01%

Fe 34.3%

S 19.96%

Common Impurities
Au, Ag, Co, Sn, Ni,
Sb, B, Cu, Pb

As_2O_3





■ Roasting process to extract gold produced 237,000 tonnes of arsenic dust as byproduct – now in underground storage



Remediation Plan Review

- Review and ongoing involvement by expert federal departments
 - Environment Canada
 - Fisheries
 - Health Canada
- Peer Review
- The remediation project is currently undergoing an Environmental Assessment
 - The scope and terms of reference have been established by the Mackenzie Valley Environmental Impact Review Board (MVEIRB).
 - The Developer's Assessment Report (DAR) is currently under development by INAC/PWGSC.
 - A decision on the project's environmental effects by the MVEIRB is required before a water licence for treatment plant discharge can be granted by the Mackenzie Land and Water Board.



Remediation Plan Elements

➤ Surface


- Pits and underground mine openings
- Tailings impoundments, sludge settling and polishing ponds
- Contaminated surficial materials (arsenic and hydrocarbon)
- Decaying mine infrastructure and buildings with severe arsenic contamination, asbestos insulation
- Junk equipment/scrap lay down areas
- Mine roads
- Alignment of Baker Creek



Remediation Plan Elements

➤ Underground

- 237,000 tonnes toxic arsenic trioxide dust stored in sealed rock chambers – in situ freezing
- Requirement for indefinite period of effluent treatment



Surface Remediation




- All existing infrastructure with no future use will be decontaminated, if necessary, and demolished prior to contaminated soils removal




Contaminated Surface Materials

Highly contaminated soils will be removed and placed in one of the open pits for freezing



B1 Pit

- Requires backfill to construct drill platform for freezing two freeze areas.
- Platform - 60,000 m³ of contaminated surficial material, >340 mg/kg As to be frozen
- 330,000 m³ of fill needed to fill pit
- 270,000 m³ will consist of waste rock, quarry rock or clean demolition debris




Other Pits

- Some pits will remain open – bermed/fenced
- Pit floors are connected to underground workings which prohibits flooding
- No source of clean backfill without added impacts




Tailings Containment Areas - 95 hectares





Tailings Cover Design – 2 Layer


- Bottom layer of broken rock has 4 functions:
 1. Physical Barrier to prevent contact with the tailings by humans or animals
 2. Prevents erosion (ATV's, Dirt Bikes)
 3. Prevent upward wicking of arsenic salts through to cover
 4. Helps prevent roots from penetrating tailings



Tailings Cover Design – 2 Layer

Upper layer of locally available silt and silty clay will:

1. Act as clean surface to shed runoff
2. Allow vegetation to establish
3. Reduce water infiltration
4. Allow for future recreational and/or traditional use
5. Eliminate airborne tailings fines on windy days




Note:
Minimizing infiltration is NOT a primary objective, but the two layer design will reduce infiltration

Effluent Treatment Plant and Settling Pond
will be covered using design similar to tailings cover




• Baker Creek Rehabilitation



Underground Remediation

Arsenic trioxide dust in underground storage is enclosed completely in rock – all access drifts sealed by cement bulkheads



Arsenic Chambers Long Section: 10 Chambers & 5 Stopes




Underground Remediation



Underground Contamination Areas




#1 > Four Separate Arsenic Trioxide Storage Areas to be Frozen




- Creating a Frozen Block



Freezing and Water Management Sequence




AREA AR 3





4 m pipe spacing

Frozen Block Events




Maintaining the Frozen Block






Hybrid thermosyphon conceptual design




Hybrid Thermosyphons Diavik Diamond Mine



Groundwater Monitoring



Giant Mine Remediation Plan



- #1 > Chamber Freezing & U/G Works
- #2 > Pits, Baker Crk & Tailings Covers
- #3 > Infrastructure Demo & HazMat
- #4 > Long Term Water Treatment

2002 Air Photograph




Public Works and
Government Services
Canada

Travaux publics et
Services gouvernementaux
Canada

Canada

Site – Post Remediation



Giant Mine – Recent Risk Mitigation Works



Rechanneling Reach 4 of Baker Creek



Baker Creek – Bitumen Liner



75 ton bridge installation over new creek alignment



Baker Creek Reach 4 - Complete



Baker Creek Reach 4 – 2009



B2 Dam Reconstruction



B2 Dam – All clay excavations had to be ripped



B2 Dam – Clay had to be heated for shaping



B2 Dam – Heating Clay at -35C



B2 Dam – Field Engineering & Challenging Geometry



Completed Baker Creek & B2 Dam





GIANT MINE 2009/10 Emerging Issues



Effluent Treatment Plant












ARSENIC CHAMBER BULKHEAD STABILIZATION




Stabilization of Bulkheads #47,48 & 49 Chamber C212







FREEZE OPTIMIZATION STUDY Chamber 10




- Forty freeze holes
- Forty instrumentation holes
- The optimization study will produce the 10 meter containment, sides and bottom as planned for all the freeze zones.
- Three types of drilling types being evaluated:
 - Rotary Mud
 - Down Hole Hammer and
 - Diamond Core

LEGEND

- | | | | |
|--|-----------------------------------|--|--|
| | Mud Rotary Hole in progress | | Abandoned Holes |
| | Down Hole Hammer Hole in progress | | Core Recovery Required (outlined marker) |
| | Diamond Core Hole in progress | | Freeze Hole by Mud Rotary |
| | Completed Borehole | | Freeze Hole by DHH |
| | | | Freeze Hole by Coring |
| | | | Freeze Hole - Method to be determined |
| | | | Instrumentation - Mud Rotary |
| | | | Instrumentation - DHH |
| | | | Instrumentation - Core |


Chamber 10 – Freeze Study



Project: Freeze Optimization Study
Drill Type: Mud Rotary

Drillhole Summary

Hole ID : P20A
Drilled by: Calibre Drilling



	Planned		Actual	
P27	Drillhole	J55 Casing	Drillhole	J55 Casing
Length (m) ¹ :	94.0	94.0	95.5	94.88
Diameter (mm):	171	114 OD	216	114 OD
Top Elev. (m):	166.0	166.6	166.0	166.86
Bottom Elev. (m):	72.0	72.0	70.5	71.98
Pipe Stick-up (m)				

Notes: 1. Planned datum is design post-site preparation ground surface; actual datum is the top of conductor pipe.
2. Planned bottom elevation of drill-hole includes 1m sub-drilling allowance.

Date	Progress
09/04/2009	•Drill to 22.5 m (2.4 m/hr drill rate)
09/05/2009	•Drill to 84.5 m (2.3 m/hr drill rate)
09/06/2009	•Drill to 95.5 m (2.9 m/hr drill rate)
Date	Notes
09/04/2009	• Moved to borehole P20A at 12:00 • Started drilling at 13:30 • Thermistor string to be installed to the freeze pipe inside the J55 casing to prevent damaging the thermistor cable
09/05/2009	• Loss of circulation at 84.5 m
09/06/2009	• Complete borehole and install J55 casing

Freeze Optimization Study



